

# LAMPIRAN HASIL INSPEKSI (CHECKSHEET)

Name & Model Plate Number		AUBUSA I-S GAT G. 1041 DFM		Exterior Color Metallic		117.60	
------------------------------	--	-------------------------------	--	----------------------------	--	--------	--

  

<b>Exterior Inspection</b> 		<b>Done Exterior part</b> Corner Stone Back Panel Fog Lamp (Max 14.7) Mud Flap (Max 14.1) <b>Rubber (Damage)</b> Head Light Tail Light Side Mirror Side Spoiler After 22 works Color Fading Line Scratches Social Dents <b>Standard of Exterior (A) 5</b> Sum Total Max 9 0-5 1 4 8-10 2 3 11-20 3 2 21-30 4 1 31 and above any		<b>Interior Inspection</b> 		<b>Other System Damages</b> Carpet Damage 1/4 Row Seat Damage Back Door Tire Damage <b>Interior Dents</b> Cylt stain Vacuum stain Heavy stain Strong Colour Heavy Colour <b>Standard of Interior (B) 2.2</b> Sum Total Max 5 0-3 1 4 4-7 2 3 8-15 3 2 14-17 any 1 18 and above any	
--------------------------------	--	--	--	--------------------------------	--	---	--

  

<b>System &amp; Function</b> Engine Oil Leakage Coolant Leakage Exhilar Sweeps Abnormal Noise Black Smoke White Smoke Idling Defect RPM Defect Defective Belt Front Suspension Rod Arm Shock Absorber Defect Alignment Brake Disc Damage Brake Defect Pedal Working Defect		<b>System &amp; Function</b> Clutch Defect Transmission Oil Leak Strut Shock Tie Rod Gear Shifting Gear Box Noise Clutch Slave Defect Clutch Master Defect Steering Defect Steering Shaft, Boss Clut Steering Wheel Steering Noise Defective Electronic TR Mutter Defect Defective Sump Wheel Bearings Defect		<b>System &amp; Function</b> Defective Meter Warning Lamp Defective A/C Horn Defect Power Window Defect Keyless or Cylinder Defect Door Lock Defect Audio Defect Seat Movement Defect Antenna Defect Electronic Mirror Defect Mirror Operation Defect Head Lamp Defect Battery Defect Jack & Tools Kit		<b>Other System Damages</b> 1 2 3 1 2 3	
---	--	--	--	---	--	---	--

  

<b>Engine &amp; System Inspection</b> Max. Damage Sum Total 5 0 4 SL 1 1-2 3 SL 1.2 3-4 2 SL 1.2.3 5-6 1 7.8 above	
---	--

  

<b>Frame - Accident Inspection</b> Front Cross Member Upper Cross Support Cross Support Front Tranny Panel Front Side Member Front Floor Center Plate Rear Cross Member		<b>Frame Name</b> Left Right 1 2 3 4 5 6 7 8		<b>Frame Name</b> Left Right 1 2 3 4 5 6 7 8		<b>Welded</b> Front Panel Rear Panel Front Panel Rear Panel Front Panel Rear Panel Front Panel Rear Panel		<b>Welded</b> Left Right 1 2 3 4 5 6 7 8	
---	--	---	--	---	--	---	--	---	--

  

<b>Frame Evaluation Standard (E)</b> Maximum damage level No frame damage Maximum Level 1 Maximum Level 2 Maximum Level 3		<b>GROUPS FINAL EVALUATION</b> Exterior (A) Interior (B) Engine (C) Frame (D) Total Score (A+B+C+D) Final Quality Level * Total 1 Score = 12 - 14 2 Score = 10.8 - 11 3 Score = 10.8 - 8 4 Score = 7.8 - 6 5 Score = 5.8 - 2.1	
--	--	--	--