



LAMPIRAN HASIL INSPEKSI (CHECKSHEET)

Make & Model		Plate Number		Exterior Color		Interior Color	
Honda RS 150		R 1243 DEH		Silver		Medallia	
Exterior Inspection 				Interior Inspection 			
Other Damage Headlight: ☐ Fog Lamp: ☐ Mud Flap: ☐ Rear Bumper: ☐ Rear Spoiler: ☐ Exhaust: ☐				Other Damage Passenger Area: ☐ Driver Area: ☐ Foot Rest: ☐			
Standard of Exterior (A) % Sum Total: 0-5 Max: 1				Standard of Interior (B) % Sum Total: 0-3 Max: 1			
System & Function Engine Oil Leakage: ☐ Exhaust Leakage: ☐ Fuel System: ☐ Ignition System: ☐ Brake System: ☐ Steering System: ☐ Suspension System: ☐ Drive Shaft: ☐ Clutch: ☐ Gear Shift: ☐ Drive Shaft Defect: ☐ Clutch Defect: ☐ Gear Shift Defect: ☐ Drive Shaft Defect: ☐ Clutch Defect: ☐ Gear Shift Defect: ☐				System & Function Clutch Defect: ☐ Exhaust Defect: ☐ Fuel System Defect: ☐ Ignition System Defect: ☐ Brake System Defect: ☐ Steering System Defect: ☐ Suspension System Defect: ☐ Drive Shaft Defect: ☐ Clutch Defect: ☐ Gear Shift Defect: ☐ Drive Shaft Defect: ☐ Clutch Defect: ☐ Gear Shift Defect: ☐			
Engine & System Inspection Total Points: 5				Other System Damaged Total Points: 5			
Frame Inspection Front Cross Member: ☐ Rear Cross Member: ☐ Front Side Member: ☐ Rear Side Member: ☐ Front Fender: ☐ Rear Fender: ☐ Front Door: ☐ Rear Door: ☐ Front Hood: ☐ Rear Hood: ☐				Frame Inspection Front Cross Member: ☐ Rear Cross Member: ☐ Front Side Member: ☐ Rear Side Member: ☐ Front Fender: ☐ Rear Fender: ☐ Front Door: ☐ Rear Door: ☐ Front Hood: ☐ Rear Hood: ☐			
Final Findings Group 1: 1 Group 2: 2 Group 3: 3 Group 4: 4 Group 5: 5				Final Findings Group 1: 1 Group 2: 2 Group 3: 3 Group 4: 4 Group 5: 5			
Final Evaluation Score: 14				Final Evaluation Score: 5			